| · . | Approved Figure 2005/11722 : CIA RDP80 00810A004201010002-1 CENTRAL INTELLIGENCE AGENCY REPORT | | | | |
|------------------------|--|--|--------------------------|--|--|
| | INFORMATION RE | | 25X ² | | |
| COUNTRY | East Germany | DATE DISTR 14 une 1454 | | | |
| SUBJECT | Tutow Airfield | MO OF FAGES 2 | | | |
| PLACE 25X1 ACQUIRED | | NO. OF EMCLS. | 25X ² | | |
| DATE OF INFO. | | SUPPLEMENT TO REPORT | | | |
| | | The state of the s | | | |
| 5X1 | THE STATE OF THE S | IS IS UNEVALUATED INFORMATION | 2. z. 110 | | |
| | en en | 80 (4) (4) | | | |
| LEGII LLEGII | | | | | |
| 25X1 | monstruction work at the Airticle, rec Four construction headquarters at Wer cumurol officer to the airfield for tw winter of 1953/54, most of the workers | der. This headquerters delegated a o or three days every week. In the at the field did clearing work. A le material were removed. The concrete | | | |
| ă. | by 14 April. The runway was provided w | a pond which had to be dradged and revaining strip of the runway was , construction work had not been started | | | |
| Ø. | Fig 8 to distant from the sirfield. T | the runway was obtained at a gravel pit the gravel in the pit was already covered bonate of line. This caused damages in the cases, several damaged spots were | vith ho | | |
| | | | | | |
| | CLASSIFICATION SECRET | | | | |

25X1

| SECRE | т | | |] | | 25X1 25X1 |
|--|---|---|--|---|---|--------------|
| observed in one concret | e section. I | n early A | pril, the d | amaged spot | were | |
| filled with bitumen. Te found at a depth about It was, therefore, plan work at the field. In I in Hungariar dump truck leased out each truck a these trucks frequently a narrow-gauge railroad Comment. The pre- | 4 meters und med to utili 1953, the gra as. The truck against a pay broke down, i line from t | er the suize this givel was his were the ment of line work was the gravel | rface of the ravel for finalled to the property .,500 DMO possible started of pit to the | water was ruture concr- le construct of VEB Baum or month, Ho in the constr- ceirfield. | usiole. sting ion site echanik, which wever, since nction of | |
| does not clarify the question is | mestion of th | e course | and length | of the runs | ay. No | 25X1 |
| | | | | | | |
| • • | , | | | | | |
| | | | | | | |
| a · | | 0. | | | | • |
| ** ** ** ** ** ** ** ** ** ** ** ** ** | | | | | | |
| | | | | | ÷ | |
| | | | | | | |

25X1